

Ultra-slim Digital Kitchen Scale: 0906

Instruction Manual



A wish for wellness...

- ✧ Capacity: 5kg
- ✧ Graduation: 1g;
- ✧ Adjustable measuring units: kg g / lb oz / oz / ml / fl. oz
- ✧ Save-space packaging design
- ✧ Tare and auto shut-off
- ✧ Low battery/over load indication
- ✧ With strong glass platform
- ✧ Backlight LCD display
- ✧ Power: 2 x 1.5V AAA batteries
- ✧ Item size: 23.0*17.0*2.0 cm

IMPORTANT SAFEGUARDS

CAUTION— To reduce risk of personal injury:

- Do not use the device if any part of the unit is cracked or damaged in any way.
- Handle and/or move the unit with care.
- Do not drop any liquid on the unit.
- Avoid placing any large items/objects on the scale that may cause damage to the product.

WARNING— To reduce the risk of product damage:

- If weight exceeds maximum capacity of 5kg, “Err” will be displayed. You should put off the object immediately or the scale may be damaged.
- When a battery mark displays on left bottom corner, it means the energy of battery is not enough; when low battery, “LO” will be shown on display then scale will shut off automatically.
- Keep the scale away from children.
- The scale should be put and taken with care and avoided falling down or hard impacting.
- If it does exhibit symptoms such as the display or erratic or erroneous data, try moving this product away from the source of interference or switching off that source of interference whilst you are using this product.

HOW TO USE

KEY PAD FUNCTIONS

- ON/OFF switch – press it to turn on, then press it for short time, the display will get back to zero; press it for long time to turn off.
- UNIT switch -- press this key for unit changing. G/Lb Oz/Oz /ml/ fl.oz are for option.

OPERATING INSTRUCTION

1. Put the scale on hard and stable platform;
2. Press “ON/OFF” to turn on. The LCD will display “-88888” for seconds then get back to “0”;
3. Press “UNIT” key to choose the unit you need;
4. Put the item in the middle of the scale platform, the LCD will show the accurate weight;
5. If the LCD doesn’t show “0.0”, press “ON/OFF” to reset the scale display into “0.0”
6. Press “ON/OFF” longer than 3 second, the scale would turn off.

HOW TO CALIBRATION

1. Place the scale on a level floor, press “UNIT” and “ON/OFF” at the same time, then the LCD will show random digits. Release “UNIT” and “ON/OFF” at the same time, the LCD will show “Zero”.
2. Press “ON/OFF” and the LCD will show “2kg”, put a 2kg weight in the middle of scale platform, the LCD will show “5kg”, put a 5kg weight on the scale platform, the LCD will show “PASS”, the calibration is successful. Otherwise you need to recalibrate.

CARE AND MAINTENANCE

- Please put the scale on a level floor.
- Please do not use the scale in the shaking circumstance, otherwise the reading would not be accurate.
- Do not overload the scale, otherwise it will damage the scale.
- If the LCD do not show “0.0”, please reset the scale before weighing.
- Please put the goods in the middle of the scale platform to ensure the exact weighing.
- Use scale only in room temperature environment to ensure accurate weights.
- When there is a sign of battery flashing in the left corner of the LCD display, it means the power of battery is running low.
- If the LCD show “Lo”, please change the battery.
- Please turn off scale when not in use to prevent corrosion and to sustain the scales usage.